

Tesla reportedly delays Cybertruck deliveries because of windshield wiper issues

The Tesla Cybertruck's gigantic windshield wiper isn't working for some people – and for others, it may be the reason they can't pick up their car. Users on the Cybertruck Owners Club forum have reported that Tesla has been delaying Cybertruck deliveries on short notice, and wiper issues are apparently to blame.