Tesla driver faces manslaughter charges over Texas crash that killed a woman inside her home



On the video, I saw BUTLER’s Tesla continue to increase in speed, and saw the amount of pressure being applied to the accelerator pedal also increase in speed. In about six (6) seconds, the accelerator pedal was pressed all the way down to 100%, “pedal to the metal,” and the vehicle reached a speed of 73 miles per hour, more than double the speed limit on that residential street. The Tesla continued straight towards the middle of the cul-de-sac, struck the curb of the complainant’s driveway, and went airborne towards the front of the home… I noted that the brake pedal was never pressed in the final minute before the crash.”

https://www.theverge.com/transportation/961161/tesla-fsd-katy-tx-manslaughter-charges